


Instructions for disassembly and storage

I. Disconnect rods from base plate



2. Disconnect front and rear rods in frame

- Disconnect right rod
- Disconnect left rod
- Disconnect middle rod

3. Fold frame so that all rods are parallel

4. Place frame on baseplate


5. Slide both into carrying bag



TIP: For optimal life of the product the rods should be disconnected before storage

Battenfeld[®]
Technologies, Inc.

2501 LeMone Industrial Blvd. / Columbia, MO 65201
573-445-9200 / Email: sales@battenfeldtechnologies.com



Product #I22560
Instructions #I028289
Rev. B

Brass Trap



STOP!

If you have a problem with this product, **DON'T RETURN IT TO THE STORE WHERE YOU PURCHASED IT.** Contact customer service at...

Battenfeld
Technologies, Inc.

2501 LeMone Industrial Blvd. / Columbia, MO 65201
573-445-9200 / Email: sales@battenfeldtechnologies.com
Or visit our website @ www.BTibrands.com

NOT WARRANTED AGAINST MISUSE, ABUSE, OR COMMERCIAL USE.

Limited Warranty

Every Caldwell product is warranted to be free of defects in materials and workmanship for a period of one (1) year from the date of original purchase. Caldwell will, at its option, repair or replace without charge, except for transportation costs, parts that fail under normal use and service when operated and maintained in accordance with our Instructions. This warranty does not apply to normal wear or to items whose life is dependent upon their use and care. This warranty is in lieu of all other warranties, expressed or implied and releases Caldwell, its affiliates, and its vendors from all other obligations and liabilities.



WARNING: IMPORTANT SAFETY INFORMATION!

- Always practice safe firearm handling
- Always hold the forend of the firearm when shooting off of this shooting rest or any rest. If it is not held, the recoil can cause the forend to jump out of the front bag, possibly causing damage to the firearm or injuring the shooter.


Contents

A. Base Plate

B. Brass Trap Net with installed rods



C. Storage Bag

TIP:All 4 front rods are the same length and all 4 rear rods are the same length. The 4 front rods are longer than the rear 4 rods.




Instructions for assembly and usage

1. Assemble front and rear frame by pushing rods into connectors, there are 3 connection points. 3 connection points in the front and 3 connection points in the rear.



2. Slide the 4 exposed rods into the 4 open holes on the front and rear of the base plate.





3. Brass Trap can be used on table top. Caldwell Lead Bag can be used to increase stability in windy conditions.

(Caldwell Lead Bag Sold Separate Product #777800)



Instructions for assembly and usage

4. Brass Trap can be mounted to standard tripod mounts (1/4-20 UNC mount).
5. Brass Trap can be mounted to the Caldwell DeadShot FieldPod (rear 1/4-20 UNC mount).
(Using Optics Adapter Kit) (Tripod mount not included)



Some tripod setups can blow over in windy conditions. Be sure tripod is secure in a stable position.